

P24804.A21.DOC



CFC #

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor(s) : S. U. CHOI

Certificate of Corrections Branch

Patent No. : 6,952,614 *B2*

Issued: October 4, 2005

Appl. No. : 10/757,436

Filed: January 15, 2004

For : BED TYPE HOT COMPRESS AND ACUPRESSURE
APPARATUS AND A METHOD OF CONTROLLING IT

COVER LETTER FOR REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Certificate
MAY 01 2006
of Correction

Sir:

Attached are a Request and a proposed Certificate of Correction in connection with the above-identified patent.

A check in the amount of \$100.00 is enclosed to cover the fee. The Commissioner is hereby authorized to charge any additional fees, or credit any overpayment, to Deposit Account No. 19-0089.

Respectfully submitted,
S. U. CHOI

04/27/2006 SFELEKE1 00000062 6952614

01 FC:1811

100.00 DP

William E. Lyddane
Bruce H. Bernstein
Reg. No. 29,027

William E. Lyddane
Reg. No. 41,568

April 26, 2006
GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191
(703) 716-1191

MAY 02 2006

P24804.A20.DOC



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor(s) : S. U. CHOI

Certificate of Corrections Branch

Patent No. : 6,952,614 *B2*

Issued: October 4, 2005

Appl. No. : 10/757,436

Filed: January 15, 2004

For : BED TYPE HOT COMPRESS AND ACUPRESSURE
APPARATUS AND A METHOD OF CONTROLLING IT

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Sir:

Please find attached a proposed Certificate of Correction.

Please correct the following error appearing in the printed patent which is apparently the fault of the inventors, as per the attached Certificate of Correction.

At column 10, line 31 (claim 4, line 9) of the printed patent, after "plate" insert ---by---. This appeared incorrectly on page 4, line 18 of the Preliminary Amendment filed June 22, 2004.

Therefore, it is respectfully requested that a Certificate of Correction issue in the above-identified patent as follows:


At column 10, line 31 (claim 4, line 9) of the printed patent, after "plate" insert ---by---.

MAY 02 2006

P24804.A20.DOC

Should there be any questions, the Examiner is invited to contact the undersigned at the below-listed number.

Respectfully submitted,
S. U. CHOI


Bruce H. Bernstein
Reg. No. 29,027

William E. Lyddane
Reg. No. 41,568

April 24, 2006
GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191
(703) 716-1191

MAY 02 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**Page 1 of 1PATENT NO. : 6,952,614 *B2*

APPLICATION NO.: 10/757,436

ISSUE DATE : October 4, 2005

INVENTOR(S) : S. U. CHOI

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At column 10, line 31 (claim 4, line 9) of the printed patent, after "plate" insert ---by---.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

MAY 02 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**Page 1 of 1PATENT NO. : 6,952,614 *B2*

APPLICATION NO.: 10/757,436

ISSUE DATE : October 4, 2005

INVENTOR(S) : S. U. CHOI

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At column 10, line 31 (claim 4, line 9) of the printed patent, after "plate" insert ---by---.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

MAY 02 2006